

VEHICLE INSPECTION REPORT

Customer [Sample report Melbourne](#)

Booking Code [Sample report](#)

Inspection Type [Platinum](#)

Location [Melbourne](#)

Inspector [Willem](#)

Make [BMW](#)

Date [27-06-1990](#)

Model [M5](#)

Vehicle Details

Badged [M5](#)

State Registered [Victoria](#)

Aust Compliance [11/2012](#)

Odometer KM [132966](#)

Engine Number [729753745910](#)

Number of Doors [4](#)

Transmission Type [Automatic](#)

Registration Number [Z16WPQ](#)

Body Colour [Blue](#)

Build Date [07/2012](#)

VIN Number [JTHS295739SLTG496](#)

Number of Cylinders [6](#)

Engine Type [Petrol](#)

ITEMS ON THIS REPORT ARE ONLY TESTED IF APPLICABLE TO THIS PARTICULAR VEHICLE.

THE ONUS OF THE VEHICLE'S AUTHENTICITY / VERIFICATION IS SOLELY THE RESPONSIBILITY OF THE PURCHASER.

VIN AND ENGINE NUMBERS CAN BE CHECKED FOR TAMPERING, HOWEVER, NOT GUARANTEED. ENGINE NUMBER WILL ONLY BE RECORDED FROM THE ENGINE IF CLEARLY VISIBLE, OTHERWISE COPIED FROM REGISTRATION RECORDS IF AVAILABLE.

We only inspect the components on the report checklist, further inspection may be recommended for any concern found.

Please refer to the last page for further advice and information on what we do and don't check.

PLEASE NOTE: THIS REPORT IS NOT A ROADWORTHY OR SAFETY CERTIFICATE OF ANY KIND, WHICH MAY BE NEEDED IN VARIOUS STATES FOR REGISTRATION PURPOSES.

STATEROADS ADVISES ALL PURCHASERS to check with the relevant authorities Australia wide for any type of Write - Off history PRIOR TO PURCHASE

StateRoads gives no guarantees on previous repair history nor is the vehicle's Body alignment measured or components removed. A final visual inspection of a vehicle at the point of sale is the responsibility of the purchaser. StateRoads can not be held liable for any dents/ damage or condition change after the initial inspection. Please ensure to view / print this report in colour. If unable to do so, please contact us for assistance.

This inspection does not check or guarantee previous work or quality of workmanship carried out on the vehicle. For example, whether the manufacturer's specified oils, fluids and coolants have been used. We do not decode tyres fitted, age nor load ratings.

Inspection and assessment has been by visual and noise appreciation only and no adjustment have been made nor components dismantled to confirm diagnosis. Whilst every care is taken StateRoads Vehicle Inspection cannot report about a defect if we cannot see or it does not appear during the inspection. It is in the opinion of our experienced inspectors that the items are in the condition indicated on this report.

Should there be a concern with the accuracy of this report contact StateRoads prior to any work being carried out.

THIS REPORT IS NOT A WARRANTY OR GUARANTEE, IT IS ONLY INTENDED FOR THE PERSON(S) NAMED ABOVE AND IS NOT TO BE RELIED UPON BY ANY OTHER PERSON(S) OR PURPOSE.

WHAT WE DON'T CHECK -Fuel and oil consumption, timing belts, alarm/ security system, trip meters / computers, navigation equipment / GPS, operation of TV, cassette or compact disc player, automatic switching of wipers and lights, body work water leaks. We don't check any Filters including diesel particulate filters and catalytic converters.

[Satisfactory](#): Good operational order

[General ageing](#): Some consistent wear for age and serviceable at your workshop's discretion.

[Attention needed](#): Repairs / replacement needed now

Engine and Engine Bay

Battery [Tested ok](#)
Battery Terminals [Satisfactory](#)
Alternator [Satisfactory](#)
Radiator [Pressure Tested](#)
Radiator Reservoir [Satisfactory](#)
Heater Hoses & Tap [General ageing](#)
A/C Operation [Active and operating](#)
A/C Cooling Fan [Satisfactory](#)
A/C Compressor [Slightly noisy](#)
Cooling / Fan Blade [Satisfactory](#)
Drive Belts [Cracking - replace](#)
Hydraulic Hoses [Satisfactory](#)
Fuel Pump Operation [Satisfactory](#)
F.I. Assy / Carb [Satisfactory](#)
Welsh Plugs [Satisfactory](#)
Starter Motor [Satisfactory](#)
Brake Master Cyl. [Satisfactory](#)
Cylinder Cap / Seal [Satisfactory](#)
Intake Manifold [Satisfactory](#)
Turbo Charger [Oil present on induction pipe](#)
Engine Cover [Satisfactory](#)
Washer Bottle [Satisfactory](#)
LPG System [Not applicable](#)
Eng. Stabiliser Mounts [General ageing](#)

Bat. Tray and Holder [Satisfactory](#)
Wiring Secured [Satisfactory Engine bay](#)
Radiator Pressure Test [Tested To: 14 PSI](#)
Radiator Hoses [General ageing](#)
Coolant Condition [Satisfactory](#)
Heater Hoses to Core [General ageing](#)
A/C Condensor [Satisfactory](#)
A/C Pipes and Hoses [Satisfactory](#)
Thermostat Housing [Satisfactory](#)
Water Pump Operation [Satisfactory](#)
Power Assist Steering [Satisfactory](#)
Fluid Condition [General ageing](#)
Fuel Line / Hoses [General ageing](#)
Air Filter Casing [Satisfactory](#)
Distributor [Not applicable](#)
Power Booster [Satisfactory](#)
Clutch Master / Cable [Not Applicable](#)
Emission Control Visual [Satisfactory](#)
Exhaust Manifold [Satisfactory](#)
Turbo-oil Leaks [Dampness visible](#)
Fuse Box & Cover [Satisfactory](#)
Cables [Satisfactory](#)
Oil Cap Deposits [Satisfactory](#)

Engine Condition

Compression Result (Optional) [Balance Tested](#)
Hot Engine Runs / Sound [Good](#)
Engine Exhaust Smoke [smoke on start up](#)
Engine Oil Level [Satisfactory](#)
Engine Oil Condition [Service due](#)
Engine Balance Tested [Good](#)

Cold Engine Runs / Sound [Not Tested](#)
CO2 Head Leakage Test [Pass](#)
Vehicle Diagnostic Scan [Codes detected](#)
Engine Bay Oil Leaks [Excessive various leaks](#)
Automatic Transmission Oil Condition [Not visible](#)
Cold Tested [No](#)

Note: Timing Belts and chains are not physically checked. Please refer to manufacturer's specifications for replacement intervals and service records.

We do not inspect the engine internals, which include fuel injectors, egr valves nor how much soot or carbon build up there is which can be a common problem on all diesel engines, especially in the higher km range and can impact on the life expectancy of the engine. Thorough and regular Service history, fuel additives and how the vehicle has been driven can have an impact on carbon or soot build up.

Added Notes

[No coolant or co2 leakage was detected during cooling system testing.](#)
[Engine bay oil leakage found at time of engine bay inspection.](#)
[Engine runs and sounds good also showing no internal running faults.](#)
[Turbo showing oil seeping work shop inspection needed.](#)

Under Body Drive Line

Clutch Slave / Fork Not applicable
G/Box Linkages Satisfactory
Driveshafts Satisfactory
Trans Fluid Leaks General sweats
Front CV Boots Not applicable
Front Differential Not applicable
Rear Differential Bushes cracking
Transfer Case Leaks Not applicable
Underside Oil Leaks General sweats/stains

Speedo Drive Electric
G/Box Mount General ageing
Driveshaft Uni. Joints General ageing
Trans Wires / Lines Satisfactory
Rear CV Boots General ageing
Front Diff Oil Leaks Not applicable
Rear Diff Oil Leaks Satisfactory
Engine / Trans Mounts General ageing

Note: Oil leaks cannot be detected if they are cleaned / degreased before inspection and not evident. Drum Brake assembly cannot be checked as Wheels are not removed.

Added Notes

Please be aware oil leaks can't be guaranteed because they can be cleaned before inspection is conducted

Driveline rubber bushes and / or mount bushes showing some wear cracks - monitor.

Oil dampness at driveline / under body - monitor at service intervals and repair as required.

Steering, Brakes and Suspension

Exhaust / Catalytic Satisfactory
LPG Tank Guard Not applicable

Mufflers Aftermarket

LEFT FRONT

Wheel General scratches
Steering Arms / Tie Rod Satisfactory
Strut / Shock General ageing
Hub Assembly Satisfactory
Control Arm(s) General ageing
Brake Pads 60%
Leaf / Coil Springs General ageing

Tyre 20%
Steer / Suspension Bushes General ageing
Ball Joint Satisfactory
Wheel Bearings Satisfactory
Brake Disc Rotor Minor lips
Brake Caliper & Hose Satisfactory
Sway Bar Mount General ageing

LEFT REAR

Wheel General scratches
Suspension Bushes General ageing
Strut / Shock General ageing
Brake Pads N/A drum brakes
Brake Caliper & Hose Satisfactory

Tyre 20%
Leaf / Control Arm(s) General ageing
Brake Disc Rotor light wear lip
Brake Drag Satisfactory
Wheel Bearings Satisfactory

RIGHT FRONT

Wheel General scratches
Steering Knuckle Satisfactory
Steering Arms / Tie Rods General ageing
Strut / Shock General ageing
Hub Assembly Satisfactory
Control Arm(s) General ageing
Brake Pads 60%
Leaf / Coil Springs General ageing

Tyre 20%
Steering Rack / Box General ageing
Steer / Suspension Bushes General ageing
Ball Joint Satisfactory
Wheel Bearings Satisfactory
Brake Disc Rotor Minor lips
Brake Caliper & Hose Satisfactory

RIGHT REAR

Wheel Minor scratches
Leaf / Control Arm(s) General ageing
Brake Disc Rotor Minor lips
Brake Drag Satisfactory
Wheel Bearings Satisfactory

Tyre 20%
Strut / Shock General ageing
Brake Pads N/A drum brakes
Brake Caliper & Hose Satisfactory

Note: Drum brake drums are not dismantled for inspection. Brake Disc Rotor Thickness / wear is not measured. Please note this may be a roadworthy requirement in some states. BRAKE PAD % IF SHOWN ARE REMAINING PORTION, PLEASE NOTE THAT SOME WORKSHOPS WILL SUGGEST TO REPLACE THE BRAKE PADS AS EARLY AS 40% - 50% REMAINING

Added Notes

Brake disc rotors have minor wear lips or scored.

Tyre % low - will need replacing

Wear visible at suspension components service or repair at RWC inspectors discretion or next service due.

Chassis, Body and Panels

LEFT FRONT

Windscreen Chipped/ pitted
Park / Headlight Glass Satisfactory
Door Hinges General ageing
Door Lock and Key Satisfactory

Bonnet Stay / Struts Satisfactory
Repeater / Indicator Lens Satisfactory
Door Rubber Seals General ageing

LEFT REAR

Glass / Trim Satisfactory
Boot Tailgate Support Satisfactory
Spare Wheel or Kit Run flat tyres fitted.
Moulds / Strips General ageing

Weather Seals / Rubber General ageing
Tail Light Lens Satisfactory
Jack / Tools Run flat tyres

RIGHT FRONT

Bumper / Bull Bar assy Satisfactory
Repeater / Indicator Lens Satisfactory
Door Rubber Seals General ageing

Park / Headlight Glass Satisfactory
Door Hinges General ageing
Door Lock and Key Satisfactory

RIGHT REAR

Glass / Trim Satisfactory
Sunroof Active and functioning
Bumper / Beaver Panel Satisfactory

Weather Seals / Rubber General ageing
Fuel Cap / Door Satisfactory
Tail Light Lens Satisfactory


Body Panels have been tested and paint/coating thickness has been measured with a digital meter to detect any repairs.

Added Notes

Bonnet latch operation - requires lube/service/adjustment

Minor chips/marks to windscreen, visibility ok, although replacement at discretion of RWC inspector

No structural previous accident repairs found, some minor work to paint finish detected and some shopping size dents and scratches still visible - purchaser advised to check body condition carefully before purchase for own satisfaction



Cosmetic Panel / paint = Green

Minor Scratches / Dents = Grey

Damaged / Dented = Black

Previous Body Repairs = Orange

Rust = Red

Please Note:

This inspection will not make comment on the alignment of any parts or body panels and will not be able to detect if any part of the vehicle is bent or out of its original shape. If you have any possible concerns with these items, please arrange an inspection by a registered smash repairer.

Stateroads will note larger type damage and previous accident repairs to all vehicles when conducting a full comprehensive inspection. However smaller shopping size dents, scratches or hail damage will not be noted or guaranteed due to our mobile service encountering dirty, unwashed and wet vehicles and lighting conditions on site. It is the purchaser's responsibly to re - check the inspected vehicle personally before settlement.

Interior

Floor Covering / Carpet Minor soiling
Glove Box Satisfactory
Door Trims Minor marks
Sun Visors Satisfactory
Interior Mirror Loose - needs attention
Comb. Switch Satisfactory
Front and Rear Wiper Replace blades
A/C Operation Operating ok
Fan Speed Control Active
Recycle Control Operating
Steering Wheel Grip General ageing
Pedal Rubbers Satisfactory
Console Satisfactory
Windows Operation Functioning
Front Seat Belts Satisfactory
Front Seat and Operation Attention required
Rear Cover / Parcel Tray Satisfactory
Warning Lights All functioning
Oil Pressure Light Functioning

NAVIGATION, CD and CASSETTE PLAYERS ARE NOT TESTED

Some radios require a security code for operation. Please ensure to obtain that code.

Added Notes

Interior trim and carpet is in good and clean condition showing typical wear at drivers seat for age / mileage.

See interior pictures as they also form part of this report.

Minor attention needed as noted above.

Dashboard Satisfactory
Air Vents Satisfactory
Roof Lining Satisfactory
Interior Light Operating
Exterior Mirror Satisfactory
Hazard Switch Satisfactory
Washers Empty
Heater Operation Operating ok
Air Flow Control Operating
Park Brake Operation Adjust next service
Horn Functioning
Radio Functioning
Sun Roof Operation Functioning correctly
Key / Remote 2 available
Rear Seat Belts Satisfactory
Rear Seat Operation Satisfactory
Fuel / Temp Gauges Functioning
A.B.S. and S.R.S Lights Active

Road Test Report

Inhibitor Switch Satisfactory
Clutch Ride Not applicable
Brakes (ABS) Service
Steering Good - Very slightly out
Steering Vibrations No vibration
Gear Box Synchronesh Not applicable
Rev. Under Load Satisfactory
Speedo Functioning
Trip Meter Functioning
Turbo Charger Satisfactory
Driveshaft Vibrations Good
Engine Performance Satisfactory for age
Trans Flare / Whine Satisfactory
Speed Limit When Tested 70 km/h

* 4WD Vehicles are not tested off road

* Vehicles can only be tested within the local speed limits

Added Notes

Brake shudder caused by disc rotor warpage - will need disc rotors machined / replaced to rectify.

This car performs ok showing no major driveline faults, however various items will need attention as listed above

Clutch Operation Not applicable
Brake Sink / Travel Satisfactory
Brake Shudder Minor pulsation
Road Handling Good
Steering Wheel Align Needs alignment
4x4 High and Low Not applicable
Gas Operation Not applicable
Odometer Functioning
Cruise Control Operating
Front C.V. Joints Not applicable
Ride and Comfort Good for age
Engine Smoke Satisfactory
Differential Whine Slight knocking - bushes?

Inspection Report Summary

Body Rating **REASONABLE**

Mechanical Rating **GOOD**

Interior Rating **GOOD**

Needs Attention

Needs Attention

-

General Overview

Please view photos as they form part of this report.

Service books sighted and show service history.

This inspection indicates the general vehicle condition is good showing typical wear and tear for its age and mileage.

Vehicle needs mechanical repairs. With repairs completed, should then be in a good serviceable condition.

*This vehicle has been assessed taking into consideration the kms displayed, the vehicle age and the condition of the vehicle as inspected

All vehicles are inspected as presented. In many cases vehicles are dirty / unwashed etc.

Please ensure to read this report in full including any added notes which may point out any repairs, servicing, faults or problems. Further explanation of the report is made by speaking directly with your inspector, whom will phone you after the inspection or by the end of that working day. If you were not available to take the call, please phone the inspector as a verbal explanation of the inspection report is important.

WE STRONGLY SUGGEST: A final visual inspection of the vehicle at the time of settlement, and is the responsibility of the purchaser.

StateRoads can not be held liable for any dents, Damage or Mechanical condition change or alterations after the initial inspection. Transported vehicles are commonly found to suffer damage in transit and in most cases no responsibility is taken by the transport company.

BEWARE: Always check for a clear title before purchasing a vehicle especially on private sales.

HISTORY AND P.P.S.R. ENCUMBERANCE CHECKS ARE AVAILABLE DIRECTLY FROM OUR STATEROADS OFFICE. (charges may apply).



www.vehicle-inspection.com.au

Servicing VIC, NSW, QLD, WA

P: 03 98508000 F: 0398508200 E: admin@vehicle-inspection.com.au